

PWM Output Etch Rev D

C500	3300uF/25V		
C501	100uF/16 or 25V		
C502	100uF/16 or 25V		
C503	3300uF/25V	2	
C506	100uF/16 or 25v	3	
C508	560uF/160V		
C509	.15uF	1	
C510	560uF/160V	2	
D500	MR856	1	
D501	1n4937		
D502	1n4937		
D503	1n4937		
D504	1n4937		
D505	1n4937	5	
D506	1.5KE18CA	1	
R508	50	1	Mount at PWM input PC board holes, otherwise will not fit.
R502	330		
R510	330	2	
R509	560	1	
R503	4.7 ohms		
R504	4.7 ohms		
R505	4.7 ohms		
R506	4.7 ohms		
R507	4.7 ohms	5	
R511	4.7 Ohms/1W	1	
U500	74OL6010	1	
U501	LM7812	1	Heat Sink if more than 3 MOSFETs are used
U502	IXDD414	1	Heat Sink if more than 3 MOSFETs are used
U503	LM7805	1	